



Department of
Rehabilitation & Correction

John R. Kasich, Governor
Stuart C. Hudson, Interim Director

10/19/2018

Director Scott Springhetti
Tri-County Regional Jail
4099 State Route 559
Mechanicsburg, OH 43044

RE: 2018 Annual Jail Inspection

Dear Director Scott Springhetti:

In accordance with Section 5120.10 of the Ohio Revised Code and Executive Order 92-03 of the Department of Rehabilitation and Correction, the Tri-County Regional Jail, a full service jail, was inspected on 09/19/2018. The inspection was restricted to assessing compliance with a group of standards, selected from the Standards for Jails in Ohio promulgated by the Department of Rehabilitation and Correction. The group of standards being inspected focused on Reception & Release, Classification, Security, Housing, Sanitation and Environmental Conditions, Communication, Visitation, Medical and Mental Health Services, Food Service, Recreation and Programming, Inmate Discipline, Administrative Segregation, Grievance, Staffing, and Staff Training. The inspection consisted of this Inspector receiving and/or reviewing requested documentation and/or materials, touring selected areas of the jail, and having discussions with various jail staff.

The total actual general housing capacity for the Tri-County Regional Jail is 212. On the date of the jail inspection, there were 196 inmates incarcerated in the Tri-County Regional Jail. The Ohio Department of Rehabilitation and Correction recommended housing capacity for the jail is 160, which is based upon total available living space and other requirements. Officials should maintain prisoner counts within the Department's recommended capacity figure .

The Tri-County Regional Jail (Full Service Jail) is in compliance with 112 standards, 52 "Essential", and 60 "Important".

5120:1-8-01 (A)(2); -01 (A)(5); -01 (A)(6); -01 (A)(8); -01 (A)(10); -01 (A)(11); -01 (A)(13); -01 (A)(14); -01 (A)(15); -02 (A); -02 (B)(3); -02 (B)(5); -02 (B)(6); -03 (A)(1); -03 (A)(3); -03 (A)(4); -03 (A)(5); -03 (A)(6); -03 (A)(7); -03 (B)(1); -03 (B)(3); -03 (B)(4); -03 (B)(5); -03 (B)(6); -03 (B)(7); -03 (B)(9); -03 (B)(10)(a); -03 (B)(10)(b); -03 (B)(10)(c); -03 (B)(10)(d); -03 (B)(11)(a); -03 (B)(11)(b); -03 (B)(11)(c); -03 (B)(13); -03 (B)(14); -04 (A)(1); -04 (A)(2)(a); -04 (I); -04 (L); -05 (A); -05 (B); -05 (C); -05 (D); -05 (E); -05 (F); -05 (G)(3); -05 (H)(1); -05 (H)(2); -05 (H)(4); -05 (H)(5); -05 (H)(6); -05 (L); -05 (M); -05 (O); -05 (P); -05 (Q); -06 (A); -06 (D); -06 (F); -06 (H); -07 (B); -07 (C); -07 (F); -07 (G); -07 (J); -09 (A); -09 (B); -09 (C); -09 (D); -09 (E); -09 (F); -09 (G); -09 (H); -09 (I); -09 (J); -09 (K); -09 (L); -09 (M); -09 (N); -09 (O); -09 (P); -09 (Q); -09 (R); -09 (S); -09 (T); -09 (U); -09 (V); -09 (W); -09 (X); -09 (Y); -09 (Z); -09 (AA); -10 (A); -10 (B); -10 (C); -10 (E); -10 (F); -10 (G)(1); -10 (G)(2); -11 (C); -11 (D); -12 (A); -12 (D); -12 (E); -12 (I); -15 (A); -15 (C); -15 (F); -16 (B); -17 (A); -17 (B); -17 (C);

The Tri-County Regional Jail did not comply with 3 standards, 0 "Essential", and 3 "Important". This letter is intended to serve as a basis for developing plans of action for bringing the facility into compliance with the deficiencies noted during the inspection.

5120:1-8-04 (A) (2) Housing Cells: (b) (Important) One hundred square feet with seven feet least dimension for double

occupancy, stacked bunks, one hundred ten square feet with nine feet least dimension for double occupancy, single bunks.

Comments: On the day of the inspection the double and quadruple bunked cells lack the required square footage. Jail officials should maintain jail population at the BRC.

5120:1-8-04 (A) (2) Housing Cells: (d) (Important) One hundred eighty square feet with nine feet least dimension for quadruple occupancy, two stacked bunks, two hundred fifteen square feet with twelve feet least dimension for quadruple occupancy, single bunks.

Comments: On the day of the inspection the double and quadruple bunked cells lack the required square footage. Jail officials should maintain jail population at the BRC.

5120:1-8-04 (A) (3) Dormitory Sleeping Space: (a) (Important) Fifty square feet per occupant , except forty-eight square feet in jails constructed prior to 1983, wherein the formula shall be based upon the requirements of paragraph (A)(2)(a) of rule 5120:1-8-04 of the Administrative Code.

Comments: On the day of the inspection, according to the required footage measurements provided by the facility, the dormitory areas were found to lack the required square footage. Jail officials should reduce the inmate population to the Bureau Recommended Capacity.

The Tri-County Regional Jail is in compliance with 100% of the Essential Standards and at least 90% of the Important Standards meeting the requirements of a "Compliant Jail". It should be noted however; the jail did not comply with 3 of the Important Standards upon which the facility was inspected. This letter is intended to serve as a basis for developing plans of action for bringing the facility back into compliance with the remaining deficiencies noted during the inspection.

The Bureau of Adult Detention encourages the jail to correct the remaining deficiencies noted in the inspection report prior to the next annual jail inspection. Plan of Action forms are enclosed and can be submitted through the Ohio Jail Management System (OHJMS) at www.OHJMS.Intelligrants.com. Feel free to contact the Bureau if you need assistance or clarification in this effort. The Bureau remains available to discuss the aspects of this report and to provide reference materials or assistance as desired.

Sincerely,



Stephen Holland, State Jail Inspector
Bureau of Adult Detention
1580 St Rt 56
London, Ohio 43140
Phone: (614) 981-2040
Email: stephen.holland@odrc.state.oh.us